

Zone Report

Report Date: 11/28/2019

RHWA000101 Rhino Watchguard

Zone No	Module No	Description
64000	137	CASE TAMPER
64000	144	WIRELESS DEVICE TAMPER
64000	300	SYSTEM COP RESET
64000	301	MAINS POWER
64000	302	SYSTEM LOW BATTERY
64000	305	SYSTEM REBOOT
64000	306	RP PROGRAMMING COMPLETE
64000	308	SYSTEM SHUTDOWN
64000	313	CODE (BUFFER) ERROR
64000	333	SIREN RESET
64000	338	WIRELESS SIREN BATTERY
64000	339	REAL TIME CLOCK RESET
64000	341	WIRELESS SIREN TAMPER
64000	342	WIRELESS SIREN MAINS POWER
64000	343	REAL TIME CLOCK FAIL
64000	344	JAMMING DETECTION
64000	352	BILLING FAILED
64000	353	BUSINESS PLAN ACTIVATION
64000	354	BUDGET PLAN ACTIVATION
64000	356	HOME PLAN ACTIVATION
64000	371	EXTERNAL TAMPER
64000	381	WIRELESS SUPERVISION
64000	384	WIRELESS LOW BATTERY
64000	1137	CASE TAMPER
64000	1144	WIRELESS DEVICE TAMPER
64000	1301	MAINS POWER
64000	1302	SYSTEM LOW BATTERY
64000	1308	SYSTEM SHUTDOWN
64000	1338	WIRELESS SIREN BATTERY
64000	1341	WIRELESS SIREN TAMPER
64000	1342	WIRELESS SIREN MAINS POWER
64000	1344	JAMMING DETECTION
64000	1351	TELCO FAIL RETRY LIMIT
64000	1352	BILLING SUCCESSFUL
64000	1371	EXTERNAL TAMPER

64000 1381 WIRELESS SUPERVISION

64000 1384 WIRELESS LOW BATTERY

64000 1602 PERIODIC TEST SIGNAL

64000 1624 CID BUFFER OVERFLOW
