

Zone Report

Report Date: 25/01/2023

PERM000101 Permaconn

Zone No	Module No	Description
950	0	PERMACONN - MAINS FAIL
951	0	PERMACONN - LOW BATTERY
953	0	PERMACONN - FAIL TO COMMUNICATE
954	0	PERMACONN - ENGINEERING RESET
955	0	PERMACONN - INTERFACE LEAD FAIL
956	0	PERMACONN - DIALER INTERFACE LEAD FAIL
958	0	PERMACONN - MODULE FAIL
967	0	Programming change to Permaconn Video Verification service
968	0	PERMACONN - IP PATH POLL FAIL
969	0	PERMACONN - CELLULAR NETWORK PATH POLL FAIL
970	0	PERMACONN - PERMACONN POLL FAIL
980	0	80% Data Usage
981	0	AUXILIARY 1/LAN 1
982	0	AUXILIARY 2/LAN 2
983	0	AUXILIARY 3/LAN 3
984	0	PERMACONN - PANEL ID CLASH
986	0	CCTV
995	0	95% Data Usage
999	0	100% Data Usage
120	120	ZONE TEST